CAPELLA INTERNATIONAL LIMITED WARRANTY

EFFECTIVE WITH ALL SALES BEGINNING ON JANUARY 1, 2016

Capella International warrants remanufactured engines sold for on and off highway equipment/ machinery to be free from defects in material and workmanship.

WARRANTY PERIOD

The standard warranty periods for all remanufactured engines sold by Capella International Ltd are as follows

- 24 months or four thousand hours (whichever occurs first) on rotating mass such as crankshafts, pistons, liners, connecting rods, cylinder heads and cylinder blocks.
- 12 months or two thousand hours (whichever occurs first) on fuel system components (such as: injectors, fuel pumps, etc.) and complete air system components (such as: turbochargers, etc).

ALL WARRANTY CLAIMS WILL BE ON A PRO-RATED BASIS FROM THE DATE OF INSTALLATION.

<u>CAPELLA INTERNATIONAL TD.</u> <u>RESPONSIBILITIES</u>

If a defect in material or workmanship is found during the standard 12 month warranty period, Capella International Ltd will, during normal working hours and at Capella International's facility (Outside of the UAE, warranty will be completed through a

local OEM dealer or a company authorized by Capella International Ltd.):

- Provide (at Capella International Choice) new, remanufactured or Capella International Ltd. approved repaired parts or assembled components needed to correct the defect.
- Replace lubricating oil, filters, coolant and other service items made unusable by the defect.

 Provide reasonable and customary labor needed to correct the defect, including labor for removal and installation when necessary to make the repair.

During the 24 month warranty period, if any crankshafts, pistons, liners, connecting rods or cylinder blocks fail because of a defect in material or workmanship, Capella International will, during normal working hours and at Capella International's facility:

- Provide (at Capella International Ltd. choice) new, remanufactured or Capella International Ltd. approved repaired parts or assembled components needed to correct the defect.
- Replace lubricating oil, filters, coolant and other service items made unusable by the defect.
- Provide reasonable and customary labor needed to correct the defect, including labor for removal and installation when necessary to make the repair.

Note: New, remanufactured, or Capella International Ltd. approved repaired parts or assembled components provided under the terms of this warranty are warranted for the remainder of the warranty period applicable to the product in which installed as if such parts were original components of that product. Items replaced under this warranty become the property of Independent Rebuild Specialist.

USER RESPONSIBILITIES

The user is responsible for:

Providing proof of the delivery date to the first user.

- Labor costs, except as sated under 'Capella International Ltd. responsibilities'.
- Premium or overtime labor costs.
- Travel or transporting costs, except as stated under Capella International Ltd. responsibilities.
- Parts shipping charges in excess of those that are usual and customary.
- Local taxes, if applicable.
- Costs to investigate complaints, unless the problem is caused by a defect in Capella International Ltd. material or workmanship.
- Giving timely notice of a warrantable failure and promptly making the product available for repair.
- Performance of required maintenance (including use of proper fuel, oil, filters, lubricants and coolant) and items replaced due to normal wear and tear.
- Allowing Capella International Ltd. access toall electronically stored data.

LIMITATIONS

Capella Internationa Ltd. is NOT responsible for:

- Failures resulting from any improper use or installation that Capella Internationa Ltd. judges improper.
- Failures resulting from attachments, accessory items, and parts not sold or approved byCapella Internationa Ltd.
- Failures resulting from abuse, neglect, or improper repair.
- Failures resulting from user's delay in making the product available after being notified of a potential product problem.
- Failures resulting from unauthorized repair or adjustments and unauthorized fuel setting changes.